energy P.

AMERICAN PETROLEUM INSTITUTE

www.api.org

## API RP 1175 Pipeline Leak Detection Management of Change



## Management of Change

## The process should include:


- Scope of the change(s)
- Clearly defined roles and approval responsibilities
  - Include stakeholders in planning
- Requirements for evaluating changes (e.g. Risk Assessment)
- Testing and test methods (as needed)
- Documentation plan
- Notification requirements (Including Controllers and shift workers)
- Training
- Special situations
  - Emergencies
  - Short term changes





www.api.org

## Management of Change





The MOC process should include the requirements of API RP 1167, Section 14 and API RP 1160, Section 13